



First floor storage space to be converted into an ADA single use restroom. The book cart elevator has been decommissioned for years. It will be removed to open the space. The pocket door will be replaced with an automatic door for ease of use by people with physical disabilities and families with strollers. One section of large print shelving will be removed. This space became functional library space in 1965.




Inside the first floor storage space to be converted to an ADA single use bathroom. 15 ft. x 12 ft. The current utility sink is already connected to plumbing and functional. An air vent to the outside and floor drain will need to be installed. This space became a work room for staff in 1965. It is unknown when it became storage.



There is no new construction and no change to the outside of the facility. Insignificant ground disturbance for a drain install and connection to water/sewer line.



Second floor hallway leading to two public restrooms on the left side of the photo. The fire doors will be moved forward to align with the drinking fountain. This allows for the restroom doors to be relocated and the doorways to be expanded to meet ADA requirements. This area upstairs technically does not qualify for review as it was part of a 1985 addition.






The center utility closet will be eliminated to expand the two second floor restrooms to meet ADA requirements. The HVAC duct will be relocated.









The second floor ladies' room has taken a beating since 1985. The stalls and hardware are rusted. The Township had to build the legs for the sink as the old components broke due to heavy use and children being set on the sink counter. The sink pipes are exposed and many floor tiles are broken. The ventilation is very poor. As noted in the photos, neither stalls are ADA compliant.



The second floor mens' room has fared slightly better over 38 years. However, the stall is only ambulatory, not ADA compliant. The stall wall, door and fixtures are rusted. There is no new construction for the second floor restrooms.